

Ordnance and Tactical Systems

Niceville, FL

equired

4. SQAR Detail Description

The Seller shall maintain a Manufacturing Management Program that is certified to AS6500 (latest revisions). The Seller must provide adequate evidence that the Manufacturing Management Program has been successfully audited by a third party registrar. A copy of the third party certificate shall be forwarded to the General Dynamics OTS Buyer. In the event that the Seller's Manufacturing Management Program loses certification, the Seller must notify the General Dynamics OTS Buyer within 24 hours in writing of the Seller's plan to attain recertification.

5. Disclaimer

The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.

SQAR-56.docx Page 1 of 1